

型号 Item No.	T-500	T-600	T-700
工作台 / Worktable			
工作台尺寸(mm) Worktable Size	600*400	700*400	800*400
T型槽 (宽*槽数*间距) (mm) T-slot (Width x No. x Distance)	14*3*100	18*3*100	18*3*100
最大载重 (kg) Max.loading Capacity	200	250	250
行程 / Travel			
X/Y/Z轴行程 (mm) X/Y/Z-axis Travel	500/400/350	600/400/350	700/400/350
主轴鼻端至工作台面距离 (mm) Distance From Spindle Nose To Worktable	170~520	150~500	150~500
主轴 / Spindle			
主轴样式 Spindle Taper	BT30 (Direct drive type)	BT30 (Direct drive type)	BT30 (Direct drive type)
主轴转速 (rpm) Spindle Rotation Speeds	15000/20000	15000/20000	15000/20000
主轴马达 (kw) Spindle Motor	5.5	5.5	5.5
进给 / Feed			
X/Y/Z快速进给速率 (m/min) X、Y、Z axis rapid feedrate	48*48*48	48*48*48	48*48*48
自动换刀系统 / ATC			
自动换刀型式 Automatic Tool Changer Type	夹臂式 (或伺服刀库) Clamp-arm Type (Optional: Servo Tool Magazine)	夹臂式 (或伺服刀库) Clamp-arm Type (Optional: Servo Tool Magazine)	夹臂式 (或伺服刀库) Clamp-arm Type (Optional: Servo Tool Magazine)
自动换刀刀把数量 (pcs) Automatic Tool Change Quantity	16/21	16/21	16/21
机床尺寸重量 / Dimension & Weight			
外观尺寸 (mm) Dimensions	1800*2250*2600	1800*2300*2650	1900*2350*2700
机械重量 (kg) Weight	3500	3800	4000